Scope of	Work for Property Lo	cated at:		2970 South Clement Avenue	
	Property is: Single Far	mily 🗵	Duplex	□ Other □	
Date:	10/1/2014				
take no respo	onsibility for problems discovered	after the ins	pection dat	The City of Milwaukee, the Redevelopment Aute, or for omissions through error or oversight. The ral Block Grant or HOME programs.	
Exterior	Condition Report				
Location Site	Required Work Landscaping	n/a ☑	Yes □	Note/Comments Self Help	\$ Cost
	Steps/Handrails	n/a □	Yes ☑		\$ 100.00
	Service walks	n/a ☑	Yes □		\$
	Fencing	n/a ☑	Yes □		\$
	Parking	n/a ☑	Yes □		\$
	Retaining walls	n/a ☑	Yes □		\$
	Other	n/a □	Yes □		\$
_	Other	n/a □	Yes □		\$
Garage	Singles: repair	n/a ☑	Yes □		\$
	Shingles: Roof over existing	n/a ☑	Yes □		\$
	Shingles:Tear off & re-roof	n/a □	Yes ☑	Including repairing fire damage	\$ 4,000.00
	Gutters/downspouts	n/a ☑	Yes □		\$
	Flashing	n/a ☑	Yes □	-	\$
	Eaves	n/a □	Yes ☑		\$ 200.00
	Siding	n/a □	Yes ☑		\$ 500.00
	Doors	n/a □	Yes ☑		\$ 350.00
	Windows	n/a ☑	Yes □		\$
	Slab	n/a □	Yes ☑	Interior step	\$ 100.00
	Paint	n/a □	Yes ☑		\$ 150.00
	Electrical	n/a □	Yes ☑		\$ 200.00
Porches	Other	n/a □	Yes ☑	Address labels	\$ 25.00
	Roof	n/a ☑	Yes □		\$
	Deck-upper	n/a ☑	Yes 🗆		\$
	Decklower	n/a ☑	Yes □	-	\$
	Steps/handrails	n/a □	Yes ☑		\$ 150.00
	Ceiling	n/a ☑	Yes 🗆		\$
	Guardrails	n/a 🗆	Yes ☑		\$ 300.00
	Structural	n/a ☑	Yes □		\$
	Paint	n/a 🗆	Yes 🗹	-	\$ 500.00

n/a ☐ Yes ☑ Rear porch skirting

Other

150.00

\$

House

Chimney	n/a □	Yes ☑		\$ 300.00
Shingles: repair	n/a ☑	Yes □		\$
Shingles: Roof over existing	n/a ☑	Yes □		\$
Shingles:Tear off & re-roof	n/a ☑	Yes □		\$
Gutters/downspouts	n/a □	Yes ☑	Seal receiver	\$ 35.00
Flashing	n/a ☑	Yes □		\$
Eaves	n/a □	Yes ☑		\$ 250.00
Siding	n/a _☑	Yes □	_	\$
Storm Doors	n/a □	Yes ☑		\$ 550.00
Prime ("main") Doors	n/a ☑	Yes 🗆		\$
Storm Windows	n/a ☑	Yes □		\$
Prime ("main") Windows	n/a □	Yes ☑	Basement glass & screens	\$ 200.00
Paint	n/a □	Yes ☑		\$ 800.00
Foundation	n/a □	Yes ☑	Tuckpoint	\$ 50.00
Electrical	n/a ☑	Yes □		\$
Other	n/a □	Yes ☑	Entry door lockset	\$ 120.00
Other	n/a □	Yes ☑	Basement hatchway cover	\$ 250.00
Other	n/a □	Yes 🗆		\$
Other	n/a □	Yes □		\$

Exterior: Estimated Cost:*

9,280.00

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.

Interior Co	ondition Report				
	Unit: Entire unit (single family) Upper unit of duplex	✓		Lower unit of duplex ☐ Other ☐	
	Required Work				
Heating	Repair/replace boiler	n/a <u></u>	Yes □		\$
	Repair radiation	n/a ☑	Yes □		\$
	Repair/replace furnace	n/a ☑	Yes □		\$
	Repair ductwork	n/a ☑	Yes □		\$
	Replace thermostat	n/a ☑	Yes □		\$
	Repair/replace grilles	n/a ☑	Yes □		\$
	Tune boiler/furn. insp ht exchang	€n/a □	Yes 🗵		\$ 350.00
Electrical	Repair/replace receptacles	n/a □	Yes ☑		\$ 300.00
	Repair/replace switches	n/a ☑	Yes □		\$
	Repair/replace fixtures	n/a ☑	Yes □		\$
	Install outlets and circuits	n/a ☑	Yes □		\$
	Install outlets and circuits	n/a ☑	Yes □		\$
	Install outlets and circuits	n/a ☑	Yes □		\$
	Install outlets and circuits	n/a ☑	Yes □		\$
	Upgrade service	n/a _□	Yes ☑		\$ 2,000.00
	Other	n/a □	Yes □		\$
	Other	n/a □	Yes □		\$
Plumbing	Repair/replace kitchen sink	n/a □	Yes ☑	Trap	\$ 135.00
	Repair/replace kitchen sink fauce	en/a ☑	Yes □		\$
	Repair/replace tub	n/a ☑	Yes □		\$
	Repair/replace tub faucet	n/a ☑	Yes □		\$
	Repair/replace toilet	n/a ☑	Yes □		\$
	Repair/replace lavatory	n/a □	Yes ☑	Trap	\$ 135.00
	Repair/replace lavatory faucet	n/a ☑	Yes □		\$
	Repair/replace wash tub	n/a ☑	Yes □		\$
	Repair/replace wash tub faucet	n/a □	Yes ☑		\$ 750.00
	Unclog piping:	n/a ☑	Yes □		\$
	Repair drain/waste/vent piping	n/a 🗹	Yes □		\$
	Repair water piping	n/a 🗹	Yes □		\$
	Repair/replace water heater	n/a □	Yes ☑	Install gas line drip leg & correct vent pipe	\$ 125.00
	Other	n/a □	Yes 🗆		\$

\$

n/a 🗆 Yes 🗆

Other

Replace broken glass	n/a ☑	Yes			\$	
Repair or replace sash	n/a ☑	Yes			\$	
Repair or replace doors	n/a ☑	Yes			\$	
Repair or repl. locks/latches	n/a ☑	Yes		Self Help	\$	
gs Repair or repl. @ defective	n/a ☑	Yes			\$	
Repair or repl. @ defective	n/a □	Yes	IJ		\$	600.00
	.,,,				Ψ	
Install smoke/CO alarm:bsmt.	n/a □	Yes	7	Self Help	\$	60.00
Install smoke/CO alarm: 1st flr.	n/a □	Yes	1	Self Help	\$	60.00
Install smoke/CO alarm: 2nd flr.	n/a □	Yes	√	Self Help	\$	60.00
Repair/replace defective	n/a _□	Yes	7	Self Help	\$	250.00
Repair defective	n/a □	Yes	v		\$	850.00
•						300.00
nepail delective						
	n/a □	Yes	✓	Bsmt column shim block repair	\$	200.00
	n/a □	Yes		_	\$	
	n/a □	Yes			\$	
	n/a □	Yes		~	\$	
				Interior: Estimated Cost:	\$	6,175.00
				Total Exterior and Interior Cost:*	\$	15,455.00
	Repair or replace sash Repair or replace doors Repair or repl. locks/latches gs Repair or repl. @ defective Repair or repl. @ defective Install smoke/CO alarm:bsmt. Install smoke/CO alarm: 1st flr. Install smoke/CO alarm: 2nd flr.	Repair or replace sash n/a Repair or replace doors n/a Repair or repl. locks/latches n/a Repair or repl. @ defective n/a Repair or repl. @ defective n/a Install smoke/CO alarm:bsmt. n/a Install smoke/CO alarm: 1st flr. n/a Install smoke/CO alarm: 2nd flr. n/a Repair/replace defective n/a Repair defective n/a Repair defective n/a Repair defective n/a n/a n/a n/a n/a n/a n/a n/a	Repair or replace sash n/a	Repair or replace sash	Repair or replace sash	Repair or replace sash n/a

Inspected by: Mark Stack Date: 10/1/2014

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway.

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.